
TOLEDO STATE (5S4) 1 SW UTC-8(-7DT) N44°36.06' W123°56.38'

SEATTLE

12 NOTAM FILE MMV

RWY 13-31: H1750X40 (ASPH)**RWY 13:** Trees.**RWY 31:** Trees.

AIRPORT REMARKS: Unattended. Deer and waterfowl invof of arpt. PPR for use—amgr. Rwy 13-31 trees in trsn area; curve apch path fm over water due to obstns. 20' trees in trsn sfc 5—75' fm rwy edge. may be flooded durg high tides. 10' trees and brush 0-20' fm rwy end 50' R of cntrln. 30' trees 80' fm rwy end 85 L. Rwy 13 end, 4 ft ditch 10 ft off pavement. Driftwood on sfc psbl. Sfc cond not rptd. Rwy 13-31 markings smlr than std.

AIRPORT MANAGER: 503-378-4880**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

TURNO N44°50.85' W122°57.06' NOTAM FILE SLE.

SEATTLE

NDB (MHW) 266 SL 312° 4.3 NM to McNary Fld. 63/17E.

VALE
MILLER MEML AIRPARK (S49) 1 SW UTC-7(-6DT) N43°57.83' W117°15.56'

KLAMATH FALLS

2249 B NOTAM FILE MMV

RWY 18-36: H3872X65 (ASPH) LIRL**RWY 18:** Thld dspclcd 880'. Road.**RWY 36:** Thld dspclcd 125'. Tree.**RWY 10-28:** 2100X40 (GRVL)**RWY 10:** Tree.**RWY 28:** Tree.**SERVICE:** LGT ACTVT LIRL Rwy 18-36—CTAF.**AIRPORT REMARKS:** Unattended. Rwy 18 has a 660' turf/grvl ovrn.**AIRPORT MANAGER:** 208-514-8647**COMMUNICATIONS:** CTAF/UNICOM 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Salt Lake ARTCC at 801-320-2568.

VERNONIA MUNI (Ø5S) 2 W UTC-8(-7DT) N45°51.13' W123°14.57'

SEATTLE

650 NOTAM FILE MMV

RWY 09-27: 2940X45 (TURF)**RWY 09:** Fence. Rgt tfc.**RWY 27:** Road.

AIRPORT REMARKS: Unattended. Hangars 100' rgt of cntrln on AER 27. Rwy 09, 4' fence at rwy end marked by orange pylons. Rwy 27 10' road 10' from rwy end. Deer and elk on and in vicinity of airport. Rwy 09-27 rwy edge marked with white mats.

AIRPORT MANAGER: 503-709-4075**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Portland Apch at 503-493-7545.

WAKONDA BEACH STATE (See WALDPORT on page 212)

WALDPORT
WAKONDA BEACH STATE (R33) 3 S UTC-8(-7DT) N44°23.07' W124°05.11'

KLAMATH FALLS

41 NOTAM FILE MMV

RWY 16-34: 2000X30 (TURF)**RWY 16:** Trees.**RWY 34:** Trees.

AIRPORT REMARKS: Unattended. Owner advises ctc Oregon Dept of Aviation 503-378-4880 prior to use. Ldg to the south and tkf to the north not recommended. Rwy sfc may be soft after extv winter rains. Standing water may be present durg hyv rain. Many 10-35' trees at 30-250' from rwy end both sides of centerline in apch area. Numerous other 2-6' trees within 50' of rwy end both sides of centerline. Rwy 34 curve apch from southwest to avoid high terrain and trees rgt at 800'. Rwy 34 has rising terrain and ditch 7' wide and 2' deep at 10' from thld. Rwy 16 has a road, +30' trees, and a p-line across the apch path within 50' of rwy end. +30' trees at 70-90' from rwy along both sides. Rwy 16-34 white tires mark rwy ends. Sfc conds not rptd.

AIRPORT MANAGER: 503-378-4880**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.