

COLLEGE PLACE

MARTIN FLD (S95) 1 W UTC-8(-7DT) N46°02.82' W118°25.03' SEATTLE
L-13A
750 NOTAM FILE SEA
Rwy 05-23: H3819X60 (ASPH) S-12 LIRL(NSTD)
Rwy 05: VASI(V2L).
Rwy 23: VASI(V2R). Road.
SERVICE: S2 **FUEL** 100LL **LGT** Rwy 05-23 NSTD LIRL southwest 1240' medium ints. Arpt lgtg opr from dusk until 1000Z. **ACTIVATE** NSTD LIRL Rwy 05-23 and VASI Rwy 05 and Rwy 23—CTAF.
AIRPORT REMARKS: Attended Mon-Fri 1600-0100Z. Call in advn 509-386-0000. 24 hr self svc credit card fueling facility. Gliders and other acft perform ops on turf btn Rwy 05-23 and twy. Overnight parking fee of \$3.00. Pvt road crosses 700' from southwest end of rwy. 2/3 of the rwy has wdspr, opn, unsealed cracks and joints, hi lvl of raveling and alligator cracking. Ldg fee.
AIRPORT MANAGER: 509-386-0000
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Spokane Apch at 509-742-2525, when Apch clsd ctc Seattle ARTCC at 253-351-3694.
RADIO AIDS TO NAVIGATION: NOTAM FILE ALW.
WALLA WALLA (VL) (DH) VORW/DME 116.4 ALW Chan 111 N46°05.22' W118°17.55' 231° 5.7 NM to fld. 1150/14E.
VOR unusable:
016°-071° byd 31 NM blo 12,500'
032°-042° byd 40 NM blo 12,500'
032°-042° byd 62 NM
042°-169° byd 40 NM
071°-101° byd 20 NM blo 14,500'
101°-146° byd 20 NM blo 13,500'
256°-285° byd 40 NM
286°-296° byd 40 NM blo 4,000'
286°-296° byd 50 NM
291°-302° byd 40 NM
309°-319° byd 40 NM blo 4,000'
309°-319° byd 85 NM
320°-031° byd 40 NM
DME unusable:
071°-101° byd 20 NM blo 14,500'
116°-071° byd 31 NM blo 12,500'
146°-151° byd 20 NM blo 11,500'

COLVILLE MUNI (63S) 1 E UTC-8(-7DT) N48°32.65' W117°53.01' SEATTLE
1883 B NOTAM FILE SEA
Rwy 01-19: H2691X40 (ASPH) S-11 MIRL 0.5% up N
Rwy 19: Thld dsplcd 255'. Tree.
SERVICE: **FUEL** 100LL, JET A **LGT** ACTVT MIRL Rwy 01-19—CTAF.
AIRPORT REMARKS: Attended Mon-Fri 1600-0100Z. Wildlife on and invof arpt. Rwy 19 dthr 255'. Rwy 19 bright stadium lgtg 3/4 mi S. Vehicle tfc acrs rwy ends and twy. 1500'X150' Grass ldg area avbl acrs Rwy 01-19 has 50' trees and poles both ends. 6' fence at rwy end 113 R. 8' fence and road 66' fm thr; bldg 170' fm thr 36' R. Aprn and tiedown grvl; asph tiedowns W; grvl tiedowns E.
AIRPORT MANAGER: 509-685-9056
WEATHER DATA SOURCES: AWOS-3 119.275 (509) 684-8994.
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

CONCRETE

MEARS FLD (3W5) 1 S UTC-8(-7DT) N48°31.79' W121°45.49' SEATTLE
267 NOTAM FILE SEA
Rwy 07-25: H2609X60 (ASPH) S-12
Rwy 07: Trees. Rgt tfc.
Rwy 25: Trees.
SERVICE: **FUEL** 100LL
AIRPORT REMARKS: Unattended. Elk and deer freq both rwy ends and mid-fld. All patterns south of arpt.
AIRPORT MANAGER: 206-972-9181
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.
• • • • •
HELIPAD H1: H40X40 (CONC)
HELIPORT REMARKS: Helipad for emerg use only.