

FIRST AIR FLD (See MONROE on page 249)

FISHERMANS BAY SPB (See LOPEZ on page 245)

FLOATHAVEN SPB (See BELLINGHAM on page 222)

FLY FOR FUN (See VANCOUVER on page 282)

FORKS (S18) 1 SW UTC-8(-7DT) N47°56.26' W124°23.76'

SEATTLE

299 NOTAM FILE SEA

RWY 04-22: H2400X75 (ASPH) MIRL

RWY 04: Trees.

RWY 22: Tree. Rgt ttc.

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. Parallel twy marked with reflectors.

AIRPORT MANAGER: 360-374-5412

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

FRIDAY HARBOR

FRIDAY HARBOR (FHR)(KFHR) 0 SW UTC-8(-7DT) N48°31.32' W123°01.46'

SEATTLE

113 B AOE NOTAM FILE FHR

L-1E

RWY 16-34: H3402X75 (ASPH-GRVD) S-12.5 MIRL 0.8% up N

IAP

RWY 16: REIL. PAPI(P2R)—GA 4.0° TCH 43'. Bldg. Rgt ttc.

RWY 34: REIL. PAPI(P4R)—GA 3.5° TCH 42'. Trees. Rgt ttc.

SERVICE: S4 FUEL 100LL LGT ACTVT REIL Rwy 16 and 34; PAPI Rwy 16 and 34; MIRL Rwy 16-34—CTAF. Rwy 16 PAPI UNUSBL byd 3 degs right of cntrn.

NOISE: NS ABTMT procedures in effect ctc arpt mgr 360-378-4724. For noise abatement avoid tkofs btn 0600-1500Z.

AIRPORT REMARKS: Attended Mon-Fri 1600-0100Z. No attendance during holidays. Bird activity on and invof arpt. Preferred Rwy 16 in calm wind conds. Due to high concentration of ttc invof arpt recommend ldg lgts or forward visibility lgts turned on while utilizing arpt. Acft with wingspan greater than 55', 24 hr PPR, ctc arpt mgr 360-378-4724 or cell 360-317-8674. Tsnt turbine acft prkg less than 1 hr dum lctd 250 ft S of trml ramp. Customs apron located on east side of terminal ramp. Soft ground btn tiedowns NE parking area. Acft in excess of 7,500 lbs charged fee based on wt ctc arpt mgr for info. Lndg fees charged for airlines and charters.

AIRPORT MANAGER: (360) 378-4724

WEATHER DATA SOURCES: ASOS 135.675 (360) 378-8491.

COMMUNICATIONS: CTAF 128.25

® **WHIDBEY APP/DEP CON** 118.2

CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

RADIO AIDS TO NAVIGATION: NOTAM FILE BLI.


WHATCOM (H) TACAN Chan 77 HUH (113.0) N48°56.72' W122°34.76' 195° 31.0 NM to fld. 82/20E.

TACAN AZIMUTH unusable:

155°-165° byd 15 NM blo 6,000'

NDB (MHV) 284 FHR N48°30.73' W123°01.43' at fld. 41/17E. NOTAM FILE FHR.

COMM/NAV/WEATHER REMARKS: 128.25 monitored intermittently.



FRIDAY HARBOR SPB (W33) 0 NE UTC-8(-7DT) N48°32.24' W123°00.58'

SEATTLE

00 AOE NOTAM FILE SEA

WATERWAY 03W-21W: 10000X2000 (WATER)

WATERWAY 03W: Hill.

WATERWAY 12W-30W: 6000X1000 (WATER)

WATERWAY 12W: Hill.

WATERWAY 30W: Hill.

SEAPLANE REMARKS: Unattended. All tkfs should be performed N of Browns Island. Flight Notification Service (ADCUS) available. General aviation overnight ldg fee.

AIRPORT MANAGER: (360) 378-4724

COMMUNICATIONS: CTAF 128.25

CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.