

CONTINUED FROM PRECEDING PAGE

AIRPORT MANAGER: 253-982-5611

WEATHER DATA SOURCES: ASOS (253) 982-3434

COMMUNICATIONS: D-ATIS 135.825 270.1 PTD 372.2

® SEATTLE APP/DEP CON 126.5 377.15

TOWER 124.8 259.3 GND CON 118.175 279.65

COMD POST 349.4 134.1

PMSV METRO 342.3 Wx svc avbl H24 exc dur afld/twr closure. DSN 382-3434/2112, C253-982-3434/2112. All obs provided by AN/FMQ-19 automated observing sys; augmented by human obsn when nec. Full svc PMSV avbl via phone patch with comd post. Tran aircrew ctc 25 OWS dur afld closure to request wx briefing DSN 228-6598, or C520-228-6598. When possible provide 3 hr PN for all rqr briefings.

AIRSPACE: CLASS D.

RADIO AIDS TO NAVIGATION: NOTAM FILE TCM.

(T) TACAN Chan 33 TCM (109.6) N47°08.86' W122°28.50' at fld. 283/15E.

No NOTAM MP 0800-2300Z† Wed

ILS 109.9 I-MAR Rwy 16. Class 1A. Rwy 16-34 backcourse unusable. Rwy 16-34 No NOTAM MP 0800-2300Z† Tue and Thu.

ILS 108.5 I-TCM Rwy 34. Class IIE. Rwy 16-34 backcourse unusable. Rwy 16-34 No NOTAM MP 0800-2300Z† Tue and Thu.

MEAD FLYING SERVICE (7ØS) 1 N UTC-8(-7DT) N47°47.23' W117°21.49'

SEATTLE

1905 TPA-2505(600) NOTAM FILE SEA

RWY 16-34: H2481X30 (ASPH)

RWY 16: Trees.

RWY 34: Trees.

AIRPORT REMARKS: Unattended. No winter maintenance. Rwy 16 rwy markings faded. Rwy 34 rwy markings faded.

AIRPORT MANAGER: 253-880-7805

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Spokane Apch at 509-742-2522

MEARS FLD (See CONCRETE on page 224)**METALINE FALLS****SULLIVAN LAKE STATE** (Ø9S) 3 SE UTC-8(-7DT) N48°50.45' W117°17.04'

SEATTLE

2614 NOTAM FILE SEA

RWY 16-34: 1765X100 (TURF)

RWY 16: Trees.

RWY 34: Sign.

AIRPORT REMARKS: Unattended. Arpt clsd 1 Oct to 1 June exc for apvd mil and public safety/law enforcement helicopter ops. Vehicles, pedestrians, and animals on and invof arpt. Watch for gnd squirrel holes in rwy.

AIRPORT MANAGER: 360-618-2477

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

METHOW VALLEY STATE (See WINTHROP on page 283)**MONROE****FIRST AIR FLD** (W16) 2 NW UTC-8(-7DT) N47°52.28' W121°59.71'

SEATTLE

50 NOTAM FILE SEA

RWY 07-25: H2087X34 (ASPH) RWY LGTS(NSTD)

RWY 07: P-line. Rgt ttc.

RWY 25: Thld dsplcd 500'. Trees.

SERVICE: S4 LGT SS-SR. Solar powered lighting.

AIRPORT REMARKS: Attended Oct-Mar 1700Z†-dark, Apr-Sept 1700-0300Z†. Parachute Jumping. Tran tie downs have no ropes, pilots must supply own. Additional tran parking avbl SE corner of rwy. Rwy 25 acft parked in primary sfc. Rwy 07 numbers 200' E of dsplcd thr; numbers only; no cntrln. Word "MONROE" painted midfield on rwy. Rwy 07 and Rwy 25 markings are faded. Rwy 07-25 unsealed cracks and joints. Alligator cracking and vegetation through cracks and joints.

AIRPORT MANAGER: 425-239-8791

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle Apch at 206-214-4722.