

SEATTLE PAINE FLD INTL (See EVERETT on page 230)**SEKIU** (11S) 0 NW UTC-8(-7DT) N48°15.97' W124°18.84'

SEATTLE

355 B NOTAM FILE SEA

RWY 08-26: H2997X50 (ASPH) LIRL**RWY 08:** Thld dsplcd 900'. Trees.**RWY 26:** NSTD—GA 4.0° TCH 35'. Tree.**SERVICE:** LGT Rwy 26 Nstd 2 box VASI left side ngts only.**AIRPORT REMARKS:** Unattended. Deer on and invof arpt Sep-Mar. High ridge along N side of rwy. Turbulence on E end apch over water. Difficult apch when wind from N. Rwy 08-26 wdspr alligator and block cracking. Bathroom lock combination is 2608.**AIRPORT MANAGER:** 360-417-3437**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.**SEQUIM VALLEY** (W28) 4 NW UTC-8(-7DT) N48°05.88' W123°11.28'

SEATTLE

151 B NOTAM FILE SEA

L-1E

RWY 09-27: H3508X40 (ASPH) LIRL**RWY 09:** Trees. Rgt tfc.**RWY 27:** Trees.**SERVICE:** FUEL 100LL**AIRPORT REMARKS:** Unattended. Self svc fuel avbl 24 hrs. Wildlife on and invof arpt. Rwy 09-27 has 2 inch shoulder dropoff. Ldg fee.**AIRPORT MANAGER:** 360-670-3083**COMMUNICATIONS:** CTAF/UNICOM 122.7**CLEARANCE DELIVERY PHONE:** For CD ctc Whidbey Apch at 360-257-3310.**RADIO AIDS TO NAVIGATION:** NOTAM FILE SEA.**TATOOSH (VH) (H) VORTACW** 112.2 TOU Chan 59 N48°17.99'

W124°37.62' 079° 59.0 NM to fld. 1650/22E.

VOR unusable:

020°-025° byd 40 NM


085°-090° byd 40 NM

091°-101° byd 40 NM blo 15,000'

091°-101° byd 58 NM

103°-109° byd 40 NM

356°-360° byd 40 NM

**SHADY ACRES** (See SPANAWAY on page 270)