
LOWER LOON CREEK (C53) 30 SW UTC-7(-6DT) N44°48.52' W114°48.52' **GREAT FALLS**
 4200 NOTAM FILE BOI
RWY 16-34: 1200X25 (TURF-DIRT) 1.2% up S
RWY 16: Tree.
RWY 34: Brush.
AIRPORT REMARKS: Unattended. Recommend land Rwy 16, dep Rwy 34 when wind cond allow. No winter maint. Rwy not marked. Arpt lctd on a plateau 50' to 75' abv the river. Lctd in narrow winding river canyon. Rodent activity adj both sides of rwy. Stock and big game animals invof rwy.
AIRPORT MANAGER: 208-756-2271
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

MARBLE CREEK (ID8) 36 WNW UTC-7(-6DT) N44°46.41' W114°59.12' **GREAT FALLS**
 4685 NOTAM FILE BOI
RWY 04-22: 1160X20 (DIRT-TURF)
RWY 04: Hill.
RWY 22: Trees.
AIRPORT REMARKS: Winter maint NA. Use at own risk; rwy short and challenging; ops by environment equipped experienced trained backcountry pilots rcmd. Wildlife and livestock on and invof of rwy. Trees and trm in acph area both ends. High density alt, ery mrrng & late eve ops is rcmd durg summer months – amgr. Apt in canyon; timbered, high mt trm all quads. Rwy 04-22 NE end first 400' soft sand.
AIRPORT MANAGER: 208-756-2271
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 1-801-320-2568.

UPPER LOON CREEK USFS (U72) 26 NW UTC-7(-6DT) N44°35.49' W114°49.39' **GREAT FALLS**
 5500 NOTAM FILE BOI
RWY 04-22: 2500X75 (TURF-DIRT)
RWY 04: Tree.
RWY 22: Trees.
AIRPORT REMARKS: Unattended. Recommend land Rwy 22, tkf Rwy 04 when wind cond permit. Trees and high terrain on both ends of Rwy 04-22, requires a steep approach. Rwy 04-22 numerous additional obstructions on apch to both rwy ends. No winter maint. Recommended for experienced mountain pilots only. Rwy 04-22 edges and thlds marked with white rocks.
AIRPORT MANAGER: 208-879-4101
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

CHAMBERLAIN GUARD STATION

CHAMBERLAIN USFS (U79) 0 E UTC-7(-6DT) N45°22.74' W115°11.81' **GREAT FALLS**
 5765 NOTAM FILE BOI
RWY 07-25: 4100X200 (TURF-DIRT)
RWY 07: Trees.
RWY 25: Tree.
RWY 15-33: 2700X140 (TURF)
RWY 15: Trees.
RWY 33: Trees.
AIRPORT REMARKS: Unattended. Extv rodent activity on both rwys. Arpt subj tempo CLOSED ery spring to soft rwys. Rwy end 25—first 300 ft of sfc is rough. Rwy 15-33 rough and uneven sfc. Rwy 07-25 and Rwy 15-33 thrs mkd and rwys outlined with yellow rocks—barely vsb. Rwy 15-33 has +2' pipe and -2' ditch across rwy North of Rwy 07-25 int; first 300' of Rwy 33 clsd. +70 ft trees adj to all rwy edges. No fone avbl at arpt. Private Stone Breaker Arpt lctd 1 NM NE of Chamberlain USFS.
AIRPORT MANAGER: 208-634-0600
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

CHAMBERLAIN USFS (See CHAMBERLAIN GUARD STATION on page 45)
