
NOWATA MUNI (H66) 2 NE UTC-6(-5DT) N36°43.26' W95°37.52'

KANSAS CITY

679 NOTAM FILE MLC

RWY 17-35: H2500X45 (ASPH) S-4

RWY 17: Trees.

RWY 35: Trees.

RWY 05-23: 2440X45 (TURF)

RWY 05: P-line.

RWY 23: Trees.

AIRPORT REMARKS: Unattended. Rwy 05-23 clsd indefly, unusbl. Rwy unusbl. Rwy 05-23 unidentifiable; pline and road cross rwy. Rwy extremely rough & covered with tall grass & hay bales. Connector twy and apron pvmt failed. -2 ft ditch at Rwy 23 thld; -12 ft ditch 220 ft fm Rwy 35 thld. NOTE: See Special Notices—Aerobatic Practice Area.

AIRPORT MANAGER: (918) 273-3538**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.

OILLR N36°05.85' W95°53.33' NOTAM FILE TUL.

KANSAS CITY

NDB (LOMW) 338 TU 357° 6.0 NM to Tulsa Intl. 710/3E.

OKC WILL ROGERS INTL (See OKLAHOMA CITY on page 234)

OKEENE**CHRISTMAN AIRFIELD** (O65) 1 SE UTC-6(-5DT) N36°06.75' W98°18.52'

WICHITA

1208 B NOTAM FILE MLC

L-15D

RWY 17-35: H3000X60 (ASPH) S-12 MIRL

RWY 17: Tree.

SERVICE: LGT MIRL Rwy 17-35 preset low ints, to incr ints—CTAF.**AIRPORT REMARKS:** Unattended.**AIRPORT MANAGER:** 580-822-3035**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Vance Apch at 580-213-6765. When Vance Apch is clsd, ctc Kansas City ARTCC at 913-254-8508.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MLC.**KINGFISHER (H) TACAN** Chan 94 IFI (114.7) N35°48.32' W98°00.23' 312° 23.6 NM to fld. 1112/9E.

OKEMAH MUNI (F81) 2 S UTC-6(-5DT) N35°24.32' W96°18.33'

DALLAS-FT WORTH

876 B NOTAM FILE MLC

L-15E

RWY 18-36: H3400X60 (ASPH) MIRL

RWY 18: Trees.

RWY 36: Tree.

SERVICE: LGT ACTIVATE MIRL Rwy 18-36—122.9.**AIRPORT REMARKS:** Unattended.**AIRPORT MANAGER:** 918-623-1050**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Fort Worth ARTCC at 817-858-7584.