

## ANAHUAC

**CHAMBERS CO** (T00) 1 E UTC-6(-5DT) N29°46.19' W94°39.81'

21 B NOTAM FILE CXO

**RWY 12-30:** H3005X60 (ASPH) S-13 MIRL

**RWY 12:** PAPI(P2L)—GA 4.0° TCH 28'. Pole.

**RWY 30:** Road. Rgt tfc.

**RWY 17-35:** 1900X300 (TURF)

**RWY 17:** Trees.

**RWY 35:** Road. Rgt tfc.

**SERVICE:** FUEL 100LL, JET A, A1+ LGT Dusk-dawn. MIRL Rwy 12-30  
preset low intst; to incr intst ACTVT—CTAF.

**AIRPORT REMARKS:** Attended Mon-Fri 1400-2300Z†. 100LL 24 hr  
self-serve. Rwy 17-35 soft when wet. Rwy 17, PAPI Rwy 12 in Rwy 17  
apch, do not land bfr xng Rwy 12.

**AIRPORT MANAGER:** 409-267-2719

**COMMUNICATIONS:** CTAF 122.9

Ⓡ **HOUSTON APP/DEP CON** 134.45

**CLEARANCE DELIVERY PHONE:** For CD ctc Houston Apch at 281-443-5844 to  
cnl IFR call 281-443-5888.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE CXO.

**TRINITY (VL) (DL) VORW/DME** 114.75 MHF Chan 94(Y) N29°32.78'  
W94°44.85' 011° 14.1 NM to fld. 38/7E.

VOR unusable:

060°-079° byd 40 NM

080°-090° byd 40 NM blo 6,000'

080°-090° byd 50 NM blo 8,000'

091°-109° byd 40 NM

110°-190° blo 2,000'

**HOUSTON**  
L-19E, 21A, GOAW  
IAP

