

DEVINE MUNI (23R) 2 W UTC-6(-5DT) N29°08.30' W98°56.51'
 702 B NOTAM FILE SJT
RWY 17-35: H3399X60 (ASPH) S-12.5 MIRL 0.8% up S
RWY 17: PAPI(P2L)—GA 3.0° TCH 33'. Road.
RWY 35: PAPI(P2L)—GA 3.0° TCH 33'. Trees.

SAN ANTONIO
L-19C
IAP

SERVICE: S4 **FUEL** 100LL **LGT** MIRL Rwy 17-35 preset low intst; to incr intst ACTVT—CTAF.

AIRPORT REMARKS: Attended Mon-Fri dawn-dusk. Deer on and invof arpt.

AIRPORT MANAGER: 830-538-4123

COMMUNICATIONS: CTAF 122.9

Ⓡ **HOUSTON CENTER APP/DEP CON** 134.95

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE SAT.

SAN ANTONIO (VH) (H) VORTACW 116.8 SAT Chan 115 N29°38.64' W98°27.68' 212° 39.4 NM to fld. 1159/8E.

VOR unusable:

018°-022° byd 40 NM


028°-032° byd 40 NM

342°-347° byd 40 NM

355°-002° byd 40 NM blo 18,000'

NDB (MHW) 359 HHH N29°08.30' W98°56.36' at fld.

703/7E. NOTAM FILE SJT.



DICKINSON

TALON AIR HELIPORT (T34) 2 NE UTC-6(-5DT) N29°29.01' W95°00.49'

HOUSTON

28 NOTAM FILE CXO

HELIPAD H1: 40X40 (TURF)

SERVICE: S2 **OX** 1, 2, 3, 4

HELIPORT REMARKS: Attended Mon-Fri 1400-2300Z±. Ldg area not mkd. No windsock. Rcmdd apch fm the W, dept to the W. Trees in E apch close to ldg pad. Helipad H1 + 25' trees east; + 25' trees, 200' west; 21' bldg. north, + 25' trees south. Airframe rprs: Overwater flight safety/survival gear, supplies, rental, re-certification, service.

AIRPORT MANAGER: 281-339-6000

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Houston Apch at 281-443-5844 to cnl IFR call 581-443-5888.

DILLEY AIRPARK (24R) 2 NW UTC-6(-5DT) N28°41.13' W99°11.35'

SAN ANTONIO
L-20G

542 B NOTAM FILE SJT

RWY 12-30: H3400X60 (ASPH) S-12.5 LIRL 0.4% up SE

RWY 12: Trees.

RWY 30: Sign.

SERVICE: **LGT** Arpt lghts opr dusk-0500Z±. Rotating bcn OTS indefly. Rwy 12-30 LIRL OTS indefly.

AIRPORT REMARKS: Unattended.


AIRPORT MANAGER: 830-965-1624

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE COT.

COTULLA (VL) (H) VORTACW 115.8 COT Chan 105 N28°27.72' W99°07.11' 335° 13.9 NM to fld. 522/9E.



DIMMIT CO (See CARRIZO SPRINGS on page 285)