

MINEOLA WISENER FLD (3F9) 1 W UTC-6(-5DT) N32°40.60' W95°30.66'**DALLAS-FT WORTH**

430 B NOTAM FILE FTW

L-17D**RWY 18R-36L:** 3234X60 (TURF)**IAP****RWY 18R:** Trees.**RWY 36L:** Trees.**RWY 18L-36R:** H3203X40 (ASPH) S-10 LIRL 0.8% up N**RWY 18L:** Trees.**RWY 36R:** Trees.**SERVICE:** S4 **FUEL** 100LL **LGT** ACTVT LIRL Rwy 18L/36R—CTAF.

Rwy 18L-36R thr at both rwy ends mkd by three red lgts each side.


AIRPORT REMARKS: Attended continuously. 100LL fuel self-svc. Rwys

18L-36R thrs dplcd 140 ft. Rwy 36R mkd thr dplcd 140 ft. Rwy

18L-36R rwy sfc loose stones and rough patches at thrs. Rwy sked to be resurfaced mid 2025 - mid 2026. Exp arpt closure.

AIRPORT MANAGER: 903-569-1929**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **LONGVIEW APP/DEP CON** 128.75 (1200-0400Z‡)Ⓡ **FORT WORTH CENTER APP/DEP CON** 132.025 (0400-1200Z‡)**CLEARANCE DELIVERY PHONE:** For CD ctc Fort Worth ARTCC at 817-858-7584.**RADIO AIDS TO NAVIGATION:** NOTAM FILE FTW.**QUITMAN (L) DME** 114.0 UIM Chan 87 N32°52.83'

W95°22.01' 211° 14.2 NM to fld. 517.

**MINEOLA/QUITMAN****WOOD CO/COLLINS FLD** (JDD)(KJDD) 5 N UTC-6(-5DT) N32°44.53' W95°29.79'**DALLAS-FT WORTH**

433 B NOTAM FILE JDD

L-17D**RWY 18-36:** H4002X60 (ASPH) S-12.5 MIRL 0.8% up S**IAP****RWY 18:** PAPI(P2L)—GA 3.0° TCH 30'. Trees.**RWY 36:** PAPI(P2L)—GA 3.0° TCH 42'. Trees.**SERVICE:** S4 **FUEL** 100LL, JET A **LGT** Rwy 36 PAPI unusbl 6 degs left of cntrln. MIRL Rwy 18-36 SS-SR photocell. PAPI Rwy 18 and Rwy 36 opr consly.**AIRPORT REMARKS:** Attended Mon-Fri 1500-2300Z‡. Wildlife invov arpt. 100LL self serve fuel.**AIRPORT MANAGER:** 903-768-2100**WEATHER DATA SOURCES:** AWOS-3PT 118.9 (903) 768-3065.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **LONGVIEW APP/DEP CON** 128.75 (1200-0400Z‡)Ⓡ **FORT WORTH CENTER APP/DEP CON** 132.025 (0400-1200Z‡)**CLEARANCE DELIVERY PHONE:** For CD ctc Fort Worth ARTCC at 817-858-7584.**RADIO AIDS TO NAVIGATION:** NOTAM FILE FTW.**QUITMAN (L) DME** 114.0 UIM Chan 87 N32°52.83' W95°22.01' 218° 10.6 NM to fld. 517.