

BASTROP**MOREHOUSE MEML** (BQP)(KBQP) 2 SE UTC-6(-5DT) N32°45.37' W91°52.84'

168 B TPA-1201(1033) NOTAM FILE DRI

RWY 16-34: H4002X100 (ASPH) S-15.5 MIRL**RWY 16:** REIL. PAPI(P2L)—GA 3.0° TCH 50'.**RWY 34:** REIL. PAPI(P2L)—GA 3.0° TCH 50'.**SERVICE:** S2 **FUEL** 100LL **LGT** Dusk-Dawn. REIL Rwy 16 and 34;

MIRL Rwy 16-34 preset low instst dusk-dawn, to incr instst

ACTVT—CTAF. PAPI Rwy 16 OTS indef. Rwy 34 REIL OTS indefly.

AIRPORT REMARKS: Attended Mon-Fri 1315-2100Z†. Deer on and infov rwy. Self serve fuel avbl 24 hrs with credit card. Rwy 16 mkg in poor cond due to fading and mold growth. Rwy 34 cracking, fading, and mold growth on rwy mkg. Ctc aprt mgr for dsng ramp space for pub use.**AIRPORT MANAGER:** 318-281-2018**WEATHER DATA SOURCES:** AWOS-3PT 118.375 (318) 281-1443. Wind unrel.**COMMUNICATIONS:** CTAF/UNICOM 122.8Ⓡ **MONROE APP/DEP CON** 126.9 (1200-0400Z†)Ⓡ **FORT WORTH CENTER APP/DEP CON** 126.325 (0400-1200Z†)**CLEARANCE DELIVERY PHONE:** For CD ctc Monroe Apch at 318-327-5641, if unavbl, ctc Fort Worth ARTCC at 817-858-7584.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MLU.**MONROE (VL) (L) VORTACW** 117.2 MLU Chan 119 N32°31.01'

W92°02.16' 026° 16.3 NM to fld. 77/3E.

VOR unusable:

010°-040° byd 40 NM

125°-135° byd 40 NM

215°-231° byd 40 NM

232°-242° byd 40 NM blo 8,000'

232°-242° byd 83 NM

243°-255° byd 40 NM blo 7,000'

243°-255° byd 56 NM

256°-267° byd 40 NM blo 18,000'

256°-267° byd 45 NM

268°-271° byd 40 NM

272°-282° byd 40 NM blo 2,000'

272°-282° byd 51 NM

283°-315° byd 40 NM

345°-355° byd 40 NM

DME unusable:

097°-131° blo 3,000'

097°-131° byd 20 NM

TACAN AZIMUTH unusable:

097°-131° blo 3,000'

097°-131° byd 20 NM

BASTROP NDB (MHW) 329 BQP N32°45.28' W91°53.01' at fld. 159/3E. NOTAM FILE DRI.

AWOS broadcasted on NDB

MEMPHIS

L-18F

IAP

