

**MOULTRIE**

**MOULTRIE MUNI** (MGR)(KMGR) 6 S UTC-5(-4DT) N31°05.13' W83°48.17'

**JACKSONVILLE**  
H-9B, 12F, L-22J  
IAF

297 B NOTAM FILE MCN  
RWY 04-22: H6000X100 (ASPH-GRVD) S-30, D-49, 2D-98 MIRL  
0.5% up NE

RWY 04: PAPI(P2L)—GA 3.0° TCH 45'. Trees.  
RWY 22: PAPI(P2L)—GA 3.0° TCH 25'. Thld displcd 372'. Trees.  
RWY 16-34: H3878X75 (ASPH) S-12.5 0.5% up N

RWY 16: Trees.  
RWY 34: Trees.

**RUNWAY DECLARED DISTANCE INFORMATION**

RWY 04: TORA-6000 TODA-6000 ASDA-6000 LDA-6000  
RWY 22: TORA-6000 TODA-6000 ASDA-6000 LDA-5628

SERVICE: S4 FUEL 100LL, JET A+ OX 3, 4 LGT MIRL Rwy 04-22  
preset on low instst dusk-0300Z‡; to incr instst and ACTVT after  
0300Z‡—CTAF. ACTVT PAPI Rwy 04 and 22—CTAF. Twy lgts Rwy  
04-22 only.

AIRPORT REMARKS: Attended 1230Z‡—dusk.

AIRPORT MANAGER: 229-890-9464

WEATHER DATA SOURCES: AWOS-3PT 118.925 (229) 890-5320.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ VALDOSTA APP/DEP CON 126.6 (east of VAD R-360 — R-180 radials)  
132.375 (west of VAD R-360 radial) (Opr 1300-0600Z‡ Mon-Thu,  
1300-0300Z‡ Fri, 1400-2200Z‡ Sat, Sun and

hol) other times ctc

Ⓡ JACKSONVILLE CENTER APP/DEP CON 127.575

CLEARANCE DELIVERY PHONE: For CD ctc Valdosta Apch at 229-257-2207, when Apch clsd ctc Jacksonville ARTCC at  
904-845-1592.


RADIO AIDS TO NAVIGATION: NOTAM FILE MCN.

(L) DME 108.8 MGR Chan 25 N31°04.94' W83°48.25' at fld. 286.

VALDOSTA (VH) (H) VOR/DME 114.8 OTK Chan 95 N30°46.83' W83°16.78' 306° 32.6 NM to fld.  
199/2W. NOTAM FILE VLD.

VOR unusable:

- 175°-205° byd 40 NM
- 206°-216° byd 40 NM blo 3,000'
- 206°-216° byd 71 NM
- 215°-225° byd 40 NM blo 7,000'
- 215°-225° byd 66 NM
- 225°-235° byd 40 NM blo 7,000'
- 225°-235° byd 80 NM
- 236°-245° byd 40 NM



**SPENCE** (MUL)(KMUL) 4 SE UTC-5(-4DT) N31°08.26' W83°42.24'

**JACKSONVILLE**  
L-22J

292 NOTAM FILE MCN  
RWY 14-32: H4500X75 (CONC) S-65, D-90

SERVICE: S4

AIRPORT REMARKS: Unattended. Rwy condition poor. Farm and construction eqpt crossing rwy. Extsv mil tfc, 200 kts, sfc to  
3500' wi 5 NM. To avoid potential tfc conflict with MOODY AFB T-6A acct and rec adzst, all acct are requested to ann  
their arr or dep intnts on CTAF. Acft manufacturer located on arpt, acct testing and demonstration with ldgts and departure  
from apron. Parking apron has loose grvl throughout. Rwy 14-32 rwy slabs have joint seal DMG and spalling, with corner  
BRKs in places.

AIRPORT MANAGER: 229-985-1974

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc Valdosta Apch at 229-257-2207, when Apch clsd ctc Jacksonville ARTCC at  
904-845-1592.

RADIO AIDS TO NAVIGATION: NOTAM FILE VLD.

VALDOSTA (VH) (H) VOR/DME 114.8 OTK Chan 95 N30°46.83' W83°16.78' 316° 30.6 NM to fld. 199/2W.

VOR unusable:

- 175°-205° byd 40 NM
- 206°-216° byd 40 NM blo 3,000'
- 206°-216° byd 71 NM
- 215°-225° byd 40 NM blo 7,000'
- 215°-225° byd 66 NM
- 225°-235° byd 40 NM blo 7,000'
- 225°-235° byd 80 NM
- 236°-245° byd 40 NM