

LAKE CUMBERLAND RGNL (See SOMERSET on page 302)

LEBANON SPRINGFIELD/GEORGE HOERTER FLD (See SPRINGFIELD on page 303)

LEITCHFIELD—GRAYSON CO (M20) 4 SE UTC-6(-5DT) N37°23.99' W86°15.68'

782 B NOTAM FILE LOU

RWY 02-20: H4000X60 (ASPH) S-12.5 MIRL 1.9% up N

RWY 02: REIL. PAPI(P2L)—GA 3.0° TCH 27'. Thld displcd 200'. Trees.

RWY 20: REIL. PAPI(P2L)—GA 3.0° TCH 26'. Road.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 02: LDA-3800

SERVICE: FUEL 100LL LGT ACTVT REIL Rwy 02 and Rwy 20; PAPI

Rwy 02 and Rwy 20; MIRL Rwy 02-20 and rotating bcn—CTAF.

AIRPORT REMARKS: Unattended. Avbl H24 with credit card. Rwy 02-20
2% downslope for Rwy 20.

AIRPORT MANAGER: 502-379-0810

COMMUNICATIONS: CTAF/UNICOM 123.0

® **INDIANAPOLIS CENTER APP/DEP CON** 121.175

CLEARANCE DELIVERY PHONE: For CD ctc Indianapolis ARTCC at
317-247-2411.

RADIO AIDS TO NAVIGATION: NOTAM FILE BWG.

BOWLING GREEN (DH) DME 113.35 BWG Chan 80(Y) N36°57.87'

W86°25.40' 017° 27.2 NM to fld. 528.

DME unusable:

003°-030° byd 30 NM blo 7,000'

068°-072° byd 35 NM blo 5,000'

128°-178° byd 35 NM blo 5,000'

220°-309° byd 15 NM blo 5,000'

310°-002° byd 15 NM blo 10,000'

ST LOUIS

L-16J

IAP

