

GREENSBORO**AIR HARBOR** (W88) 6 N UTC-5(-4DT) N36°10.42' W79°48.18'

CINCINNATI

822 NOTAM FILE RDU

RWY 09-27: H2460X65 (ASPH-TURF) MIRL(NSTD)**RWY 09:** Trees.**RWY 27:** Trees.**SERVICE:** S4 **FUEL** 100LL **LGT** Rwy 09-27 NSTD MIRL; edge lgts vary from 60'–75' from pavement S side; 8' fm pavement N side; night landings have no indication of pvmt location.**AIRPORT REMARKS:** Attended 1700Z†—dusk. After hrs emerg call 336-669-5462. Deer on and invof arpt. Fuel avbl 24hr credit card svc. Rwy 09 rwy nrs faded Rwy 09-27 marked with yellow cones indicating rwy width up to 100'. Rwy cond poor due to rwy wid. Rwy 09-27 north 25' width is asph. South 40' width is turf. Rwy 09 has +60' drop-off 220' fm thr. Rwy 27 has 8' drop-off 10' fm thr; left and right. Rwy 09 ldg uphill. Grvl access road 60' from Rwy 27 end. Aft hangar access immediately adjacent to rwy, parked planes left side of Rwy 27.**AIRPORT MANAGER:** 336-669-5462**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Greensboro Apch at 743-222-6129.**GREENSBORO EXEC** (3A4) 8 SE UTC-5(-4DT) N35°56.52' W79°41.13'

CHARLOTTE

739 NOTAM FILE RDU

L-25E, 36F

RWY 17-35: H3064X30 (ASPH) S-8 MIRL 2.2% up S**RWY 17:** Trees.**RWY 35:** Trees.**SERVICE:** S4 **LGT** ACTVT MIRL Rwy 17-35, 5 clicks only—CTAF more than 5 lock out control for 10 min. Rwy 17-35 only two end lgts each side.**AIRPORT REMARKS:** Attended 1200-2200Z†. Parachute Jumping. Rwy 17 uphill ldg preferred. Rwy 17-35 turn-arounds are part of the rwy, there is no runoff area at either end. Rwy 17-35 numbers smaller than std. Rwy 17 has 50' drop off 60' from rwy end offset 30' both sides of centerline.**AIRPORT MANAGER:** 336-420-8623**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Greensboro Apch at 743-222-6129.**RADIO AIDS TO NAVIGATION:** NOTAM FILE RDU.**LIBERTY (VL) (L) VORTAC** 113.0 LIB Chan 77 N35°48.70' W79°36.76' 339° 8.6 NM to fld. 828/3W.