

RICHMOND CO (See ROCKINGHAM on page 363)

ROANOKE RAPIDS

HALIFAX/NORTHAMPTON RGNL (IXA)(KIXA) 8 S UTC-5(-4DT) N36°19.79' W77°38.11'

WASHINGTON

H-9C, 12H, L-35C, 36G
IAP

144 B NOTAM FILE IXA

RWY 02-20: H5500X100 (ASPH) S-45, D-65 HIRL

RWY 02: REIL. PAPI(P2L)—GA 3.0° TCH 25'. Trees.

RWY 20: MALSR. PAPI(P2L)—GA 3.0° TCH 24'. Trees.

SERVICE: **FUEL** 100LL, JET A1 + **LGT** ACTVT MALSR Rwy 20;
REIL Rwy 02; PAPI Rwy 02 & 20; HIRL Rwy 02-20—CTAF.

AIRPORT REMARKS: Attended Mon-Sat 1300-2200Z†, Sun
1700-2200Z†. For svc after hrs contact 252-578-3774.
Unattended New Years Day, Easter, Jul 4th, Thanksgiving, and
Christmas. Birds on & invof arpt. Agriculture equip ocly adj to
Rwy 02-20. 100LL and Jet-A fuel avbl 24 hrs self service w/
credit card.

AIRPORT MANAGER: 252-583-3492

WEATHER DATA SOURCES: AWOS-3PT 119.975 (252) 583-3446.

COMMUNICATIONS: CTAF/UNICOM 123.075

® **WASHINGTON CENTER APP/DEP CON** 132.025

CLEARANCE DELIVERY PHONE: For CD ctc Washington ARTCC at
703-771-3587.

RADIO AIDS TO NAVIGATION: NOTAM FILE RDU.

TAR RIVER (VL) (H) VORTAC 117.8 TYI Chan 125 N35°58.60'
W77°42.22' 014° 21.4 NM to fld. 73/5W.

VOR unusable:

048°-052° byd 40NM blo 6,000'

186°-189° byd 40 NM blo 6,000'

298°-318° byd 40 NM blo 6,000'

TAC AZ unusable:

008°-018° byd 27 NM

120°-127° byd 33 NM

284°-289°

DME unusable:

008°-018° byd 27 NM

120°-127° byd 33 NM

209°-215° byd 30 NM

287°-292° byd 38 NM

339°-347° byd 30 NM

