

**MARINA MUNI** (OAR)(KOAR) 2 NE UTC-8(-7DT) N36°40.89' W121°45.70' **SAN FRANCISCO**  
 137 B NOTAM FILE OAK **L-3B**  
**RWY 11-29:** H3483X75 (ASPH) S-20, D-50 MIRL **IAP, AD**  
**RWY 29:** PAPI(P2L)—GA 3.0° TCH 45'. Rgt tfc.  
**SERVICE:** S4 FUEL 100LL, JET A **OX** 3, 4 **LGT** ACTIVATE MIRL Rwy 11-29—CTAF 7 clicks.  
**NOISE:** Depart Rwy 29 execute 45° rgt turn to avoid overflight of noise sensitive residential area.  
**AIRPORT REMARKS:** Attended Mon-Fri 1600-0100Z†. Fuel avbl (100LL and Jet A) 24 hrs via credit card lock system.  
 Parachute Jumping. Ultralight and skydiving activity on and invof arpt. Skydiving activity on SE side of arpt. Rwy 29 calm wind rwy. 500' stopway departure end Rwy 29.  
**AIRPORT MANAGER:** 831-582-0102  
**WEATHER DATA SOURCES:** AWOS-3PT 134.025 (831) 384-2967.  
**COMMUNICATIONS:** CTAF/UNICOM 122.7  
 Ⓜ **NORCAL APP/DEP CON** 127.15 (136°-360° MRY) 133.0 (001°-135° MRY)  
**CLEARANCE DELIVERY PHONE:** For CD ctc NorCal Apch at 916-361-3748.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE SNS.  
**SALINAS (VH) (H) VORTACW** 117.3 SNS Chan 120 N36°39.83' W121°36.19' 261° 7.7 NM to fld. 81/17E.  
 VOR unusable:  
 010°-016° byd 22 NM blo 7,000'  
 010°-016° byd 26 NM blo 8,000'  
 016°-080° byd 22 NM blo 8,000'  
 109°-119° byd 40 NM blo 6,000'  
 109°-119° byd 58 NM  
 135°-250° byd 40 NM  
 150°-170° byd 8 NM blo 10,000'  
 295°-302° byd 40 NM  
 303°-313° byd 40 NM blo 18,000'  
 314°-338° byd 40 NM  
 339°-349° byd 40 NM blo 18,000'  
 350°-108° byd 40 NM  
**TACAN AZIMUTH** unusable:  
 010°-080° byd 22 NM blo 8,000'  
 150°-200° blo 11,000'  
 245°-255° byd 20 NM  
 Aerobatic acft wi an area defined as .5 NM rds of SNS 357016.4 (5.3 NM W CVH), blo 3000', avoidance advised SR-SS.  
**DME** unusable:  
 010°-080° byd 22 NM blo 8,000'  
 150°-200° blo 11,000'

**MARIPOSA-YOSEMITE** (MPI)(KMPI) 4 W UTC-8(-7DT) N37°30.65' W120°02.37' **SAN FRANCISCO**  
 2254 B NOTAM FILE RIU **L-3B, 9A**  
**RWY 08-26:** H3305X60 (ASPH) S-12 MIRL 0.9% up W **IAP**  
**RWY 08:** PAPI(P2L)—GA 4.0° TCH 36'. Tree. Rgt tfc.  
**RWY 26:** PAPI(P2L)—GA 4.5° TCH 40'. Tree.  
**SERVICE:** S2 FUEL 100LL, JET A **LGT** ACTVT PAPI Rwy 08 and 26; MIRL Rwy 08-26—CTAF.  
**AIRPORT REMARKS:** Attended Mon-Fri 1800-0000Z†. Fuel avbl 24 hrs with credit card. Parachute Jumping. Birds on and invof arpt. Rwy 08 terrain drops along both sides of twy 45' from rwy edge. Unsealed med to high svrty longl and lateral cracks in the asph pavamaent extd the entire len of Rwy 08-26 with some loose debris found scattered acrs the sfc.  
**AIRPORT MANAGER:** 209-966-5356  
**WEATHER DATA SOURCES:** AWOS-3 135.6 (209) 966-2912.  
**COMMUNICATIONS:** CTAF/UNICOM 122.7  
 Ⓜ **OAKLAND CENTER APP/DEP CON** 121.25  
**CLEARANCE DELIVERY PHONE:** For CD ctc Oakland ARTCC at 510-745-3380.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE RIU.  
**FRIANT (L) (L) VORTACW** 115.6 FRA Chan 103 N37°06.27' W119°35.73' 302° 32.3 NM to fld. 2380/17E.