

## AJO

**ERIC MARCUS MUNI** (P01) 5 N UTC-7 N32°27.17' W112°51.68'

1450 B NOTAM FILE PRC

**RWY 12-30:** H3800X60 (ASPH) S-12 MRL 0.6% up SE

**SERVICE:** L&T PAPI Rwy 12 and 30; MRL Rwy 12-30 opr SS-SR and preset low intst; incr intst—CTAF.

**AIRPORT REMARKS:** Unattended. Rwy 12-30 asph and gravel stwy 1400 ft NW end; 1065 ft stwy SE end; asph broken and brush on stwys byd 200 ft fm thrs. 2 x 2 ft exposed conc cable mrks both sides of rwy wi 20 ft of paved sfc. Rwy 30 4 ft dike 1340 ft fm thr. 6-10 ft raised panels acrs ramp 70 ft in front of T-hngrs; mkd with paint. Mt all quads. Mil jet tfc and livestock on and invof arpt. NOTE: See Special Notices—Restricted Area R-2305, Gila Bend, Arizona Transit Information.

**AIRPORT MANAGER:** 520-627-3951

**COMMUNICATIONS:** CTAF 122.9

**AJO RCO** 122.2 (PRESCOTT RADIO)

**RADIO AIDS TO NAVIGATION:** NOTAM FILE PRC.

**GILA BEND (VH) (H) VORTAC** 116.6 GBN Chan 113 N32°57.38' W112°40.46' 183° 31.6 NM to fld. 790/14E.

TACAN AZIMUTH unusable:

360°-010° byd 25 NM

VOR unusable:

091°-101° byd 40 NM blo 18,000'

102°-114° byd 40 NM blo 6,500'

102°-114° byd 53 NM blo 15,000'

102°-114° byd 79 NM

115°-189° byd 40 NM

211°-213° byd 40 NM

287°-292° byd 40 NM


293°-303° byd 40 NM blo 18,000'

304°-331° byd 40 NM

352°-090° byd 40 NM

PHOENIX

L-5B



**AK-CHIN RGNL** (See MARICOPA on page 64)

**AVI SUQUILLA** (See PARKER on page 70)