

JACKPOT/HAYDEN FLD (Ø6U) O E UTC-7(-6DT) N41°58.55' W114°39.48'

SALT LAKE CITY

5224 B NOTAM FILE RNO

H-3D, L-11C

RWY 15-33: H6180X60 (ASPH) S-12.5 MIRL 0.8% up NW

RWY 15: REIL. PAPI(P2L)—GA 4.0° TCH 40'. Trees.

RWY 33: REIL. PAPI(P2L)—GA 3.5° TCH 40'. Hill.

SERVICE: Lgt SS-SR. Bcn vis ltd fm west. ACTVT REIL Rwy 15 and Rwy 33; PAPI Rwy 15 and Rwy 33; MIRL Rwy 15-33—CTAF.

AIRPORT REMARKS: Attended on call. Fuel not avbl. Bird hazard east of arpt at ponds. Emergency contact 208-731-2447. If no wind conds, rcmd dep Rwy 15, arr Rwy 33 for slope. Terrain obstns lctd S and W of arpt.

AIRPORT MANAGER: 775-755-2447

WEATHER DATA SOURCES: AWOS-AV 120.00 (775) 755-2297.

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE TWF.

TWIN FALLS (VL) (H) VORTACW 113.1 TWF Chan 78 N42°28.79' W114°29.37' 176° 31.1 NM to fld. 4149/18E.

VOR unusable:

000°-010° byd 40 NM blo 7,000'

000°-010° byd 50 NM

011°-015° byd 40 NM

040°-091° byd 40 NM

092°-102° byd 40 NM blo 16,500'

092°-102° byd 77 NM

103°-106° byd 40 NM

107°-117° byd 40 NM blo 14,000'

107°-117° byd 64 NM blo 22,000'

118°-171° byd 40 NM

120°-160° byd 35 NM blo 12,000'

172°-182° byd 40 NM blo 13,000'

172°-182° byd 55 NM

183°-185° byd 40 NM

186°-196° byd 40 NM blo 10,600'

186°-196° byd 57 NM

197°-230° byd 40 NM

TACAN AZIMUTH unusable:

120°-160° byd 35 NM blo 12,000'

DME unusable:

120°-160° byd 35 NM blo 12,000'