

SPRINGER MUNI (S42) 1 S UTC-7(-6DT) N36°19.89' W104°37.07'

5894 B NOTAM FILE ABQ

DENVER
H-6F L-15A

RWY 01-19: H5003X60 (ASPH) S-8.5 PCN 3 F/D/Y/T MIRL

0.3% up S

RWY 01: Hiil.

SERVICE: LGT ACTVT MIRL Rwy 01-19—CTAF. MIRL Rwy 01-19 preset low intst; incr intst—CTAF.

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. Aces gate #2020. Rwy Arpt road rwy gates locked; for entry and exit call 575-483-2682 before arrival. No phone on arpt. Rwy 19 3-10 ft drop off 30 ft fm edge W side alg first 300 ft fm thr.

AIRPORT MANAGER: 575-483-2682

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE RTN.

CIMARRON (VH) (H) VORTAC 116.4 CIM Chan 111 N36°29.48' W104°52.32' 115° 15.6 NM to fld. 6550/13E.

VOR unusable:

010°-020° byd 40 NM
045°-055° byd 40 NM
140°-150° byd 40 NM
165°-175° byd 40 NM
185°-195° byd 40 NM
215°-225° byd 40 NM
230°-290° byd 20 NM blo 18,000'
250°-260° byd 40 NM
285°-295° byd 40 NM
305°-315° byd 40 NM
313°-323°
325°-335° byd 40 NM
330°-345°
340°-010° byd 34 NM blo 11,000'
350°-360° byd 40 NM

TACAN AZIMUTH unusable:

230°-290° byd 20 NM blo 18,000'
340°-010° byd 34 NM blo 11,000'

DME unusable:

230°-290° byd 20 NM blo 18,000'
340°-010° byd 34 NM blo 11,000'

