

HOOPER

FREMONT ISLAND LOWER (1UT) 10 W UTC-7(-6DT) N41°10.54' W112°22.82' SALT LAKE CITY
4634 NOTAM FILE CDC Not insp.
RWY 09-27: 1843X25 (DIRT)
RWY 27: Rgt t/c.
AIRPORT REMARKS: Upper and Lower Fremont Island arpts reqd to use CTAF freq-122.9.
AIRPORT MANAGER: 385-220-5313

FREMONT ISLAND UPPER (2UT) 9 W UTC-7(-6DT) N41°09.56' W112°19.98' SALT LAKE CITY
4654 NOTAM FILE CDC Not insp.
RWY 14-32: 1980X25 (DIRT)
RWY 14: Rgt t/c.
AIRPORT REMARKS: Upper and Lower Fremont Island arpts reqd to use CTAF freq-122.9.
AIRPORT MANAGER: 385-220-5313

HUNTINGTON MUNI (69V) 3 NE UTC-7(-6DT) N39°21.67' W110°55.02' DENVER
L-9D
IAP
5915 B NOTAM FILE CDC
RWY 08-26: H4048X75 (ASPH) S-12.5 MIRL 0.8% up W
RWY 08: Thld dsplcd 214'. Road.
RWY 26: Trees.
RWY 12-30: 3640X70 (DIRT) S-6 1.2% up NW
RWY 12: Fence.
RWY 30: Trees.
RWY 18-36: 2079X56 (DIRT) 0.6% up NE
SERVICE: **FUEL** 100LL **LGT** ACTIVATE MIRL Rwy 08-26-122.8.
AIRPORT REMARKS: Unattended. Fuel 24 hr self serve. Rwy 08-26 no line of sight between rwy ends. Small amounts of vegetation on Rwy 12-30. Small amounts of vegetation on Rwy 18-36.
AIRPORT MANAGER: 435-381-3589
COMMUNICATIONS: CTAF/UNICOM 122.8
® **SALT LAKE CENTER APP/DEP CON** 133.9
CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.
RADIO AIDS TO NAVIGATION: NOTAM FILE PUC.
CARBON (VH) (H) VORW/DME 115.5 PUC Chan 102 N39°36.19' W110°45.21' 194° 16.4 NM to fld. 5830/14E.
VOR unusable:
010°-070° byd 25 NM blo 14,000'
200°-275° byd 27 NM blo 13,000'
205°-287° byd 40 NM
275°-300° byd 25 NM blo 12,000'
288°-298° byd 40 NM blo 13,000'
288°-298° byd 53 NM
299°-107° byd 40 NM
300°-330° byd 25 NM blo 13,500'
330°-010° byd 25 NM blo 17,300'
DME unusable:
010°-070° byd 25 NM blo 14,000'
200°-275° byd 27 NM blo 13,000'
275°-010° byd 27 NM blo 17,300'
275°-010° byd 35 NM
COMM/NAV/WEATHER REMARKS: Local wx avbl on CTAF 122.8, 3 clicks.